

General Information

Date & Time: 11, Aug, 2025 15:10

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	10,684
Registration No.	DBI5281	Chassis No.	PA1B18F34P4218908
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	166.0	174	161	163
2	Boot Lid	251.0	258	252	243
3	Roof	148.7	152	153	152/138
4	Left Front Fender	143.3	150	140	140
5	Left Front Door	150.3	147	144	160
6	Center Panel Left				
7	Left Rear Door	164.6	178	161	155
8	Left Back Panel	148.6	157	141	148
9	Right Front Fender	156.6	155	157	158
10	Right Front Door	117.3	124	109	119
11	Center Panel Right				
12	Right Rear Door	128.0	120	131	133
13	Right Back Panel	142.0	130	139	157

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Minimal / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small</p>	<p>Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Without warranty booklet and tools. With spare tire, jack and leather seat cover. Leather armrest on every door trim. Molds at center cup holder. 1 key. With LTO plate.</p>