

General Information

Date & Time: 08, Aug, 2025 09:31

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	37,286
Registration No.	CCA1542	Chassis No.	PA1B18F34P4221582
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	94.2	102	90	91
2	Boot Lid	106.9	96	111	114
3	Roof	97.3	100	87	100/102
4	Left Front Fender	93.8	95	87	100
5	Left Front Door	271.6	274	264	277
6	Center Panel Left				
7	Left Rear Door	101.1	113	94	96
8	Left Back Panel	101.9	110	97	99
9	Right Front Fender	95.0	102	88	95
10	Right Front Door	93.7	93	91	97
11	Center Panel Right				
12	Right Rear Door	94.7	98	91	95
13	Right Back Panel	97.8	96	91	107

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Medium</p>	<p>Remarks (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Front Door, Molding - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Large / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with warranty booklet/with spare tire and jack/ incomplete tools/ with LTO plate</p>