

General Information

Date & Time: 08, Aug, 2025 10:55

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	29,017
Registration No.	NFC5128	Chassis No.	PA1B18F31P4207087
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.6	113	111	120
2	Boot Lid	122.0	120	122	124
3	Roof	95.8	104	92	94/93
4	Left Front Fender	98.4	99	94	102
5	Left Front Door	101.2	101	100	103
6	Center Panel Left				
7	Left Rear Door	106.0	109	108	101
8	Left Back Panel	105.6	111	103	103
9	Right Front Fender	103.0	109	94	106
10	Right Front Door	101.8	96	100	110
11	Center Panel Right				
12	Right Rear Door	99.0	88	100	109
13	Right Back Panel	103.2	107	96	107

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium / Ceiling - Grime - Minimal / (L) Front Seat - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes		Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Dent - Large / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Dent - Small / Roof - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal	
Frame Evaluation :	A	Functional Evaluation :	A
Remarks Defects not found		Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist	

Inspector Notes

with LTO plate, no warranty booklet, with jack and incomplete tools, with spare tire