


General Information

Date & Time: 08, Aug, 2025 10:35

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	35,878
Registration No.	NHQ7653	Chassis No.	PA1B18F33P4238700
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	117	107	117
2	Boot Lid	102.3	103	100	104
3	Roof	106.9	104	105	100/119
4	Left Front Fender	103.6	108	101	102
5	Left Front Door	101.0	99	100	104
6	Center Panel Left				
7	Left Rear Door	105.3	117	104	95
8	Left Back Panel	115.6	131	111	105
9	Right Front Fender	103.4	105	98	107
10	Right Front Door	105.0	108	104	103
11	Center Panel Right				
12	Right Rear Door	105.0	103	105	107
13	Right Back Panel	116.3	108	116	125

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / (L) Front Floor Mat - Cut, Crack - Medium / Overall Interior - Smell - Yes / Ceiling - Grime - Small / Mat Other - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Seat - Worn - Yes / (L) Front Floor Mat - Worked - Small	Remarks (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, no jack, incomplete tools, with spare tire, with LTO plate, scratches on tail light, resin stain on trunk and engine hood and roof,