

General Information

Date & Time: 08, Aug, 2025 10:07

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	7,794
Registration No.	NKK5365	Chassis No.	PA1B18F36R4273332
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.8	96	96	105
2	Boot Lid	95.2	90	99	97
3	Roof	87.6	95	93	71/92
4	Left Front Fender	89.4	98	88	83
5	Left Front Door	91.8	89	88	99
6	Center Panel Left				
7	Left Rear Door	92.5	102	89	87
8	Left Back Panel	100.0	108	100	92
9	Right Front Fender	317.3	159	151	642
10	Right Front Door	94.6	101	92	91
11	Center Panel Right				
12	Right Rear Door	93.3	86	90	104
13	Right Back Panel	102.4	98	99	111

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Mat Other - Grime - Medium / (R) Front Floor Mat - Grime - Medium / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Medium / (R) Front Trim - Grime - Medium</p>		<p>Remarks (R) Front Fender - Repair Traces - Yes / (L) Front Door, Molding - Scratch - Large / (L) Front Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Fender, Molding - Scratch - Medium / (R) Front Fender, Molding - Repair mark - Difference in Color / Front Bumper, Grille, Lamps - Repair mark - Yes / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Medium / (L) Rear Door, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Medium</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Defects not found</p>	

Inspector Notes
with warranty booklet/ with jack and spare tire/ with LTO plate and tools