

General Information

Date & Time: 08, Aug, 2025 12:52

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	70,518
Registration No.	NFR4327	Chassis No.	PA1B18F30R4247339
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	140.3	142	137	142
2	Boot Lid	122.6	119	121	128
3	Roof	123.7	123	135	121/116
4	Left Front Fender	122.0	124	121	121
5	Left Front Door	121.3	122	124	118
6	Center Panel Left				
7	Left Rear Door	120.6	124	120	118
8	Left Back Panel	129.6	139	124	126
9	Right Front Fender	135.3	136	135	135
10	Right Front Door	107.0	109	106	106
11	Center Panel Right				
12	Right Rear Door	118.6	119	119	118
13	Right Back Panel	127.3	125	126	131

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Minimal / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Medium / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Cut, Crack - Small / (L) Front Seat - Grime - Minimal</p>	<p>Remarks (L) Rear Door, Molding - Scratch - Medium / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Dent - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Wiper - Function - Weak / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Wiper issue. Without warranty booklet, tools and seat cover. With spare tire and jack. 1 key. With LTO plate.</p>