

General Information

Date & Time: 11, Aug, 2025 17:14

Make	Toyota	Model	Lite Ace
YOM	2024	Odo Meter Reading	6,945
Registration No.	EAJ5181	Chassis No.	MHKB3FE10RK004206
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Utility Cargo
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	73.7	72	81	68
2	Boot Lid	64.9	58	88	49
3	Roof	63.9	68	51	67/70
4	Left Front Fender	63.7	56	60	76
5	Left Front Door	55.2	57	54	55
6	Center Panel Left				
7	Left Rear Door	60.9	60	57	65
8	Left Back Panel	66.4	67	62	70
9	Right Front Fender	66.9	68	55	78
10	Right Front Door	53.9	51	54	56
11	Center Panel Right				
12	Right Rear Door	59.4	56	65	58
13	Right Back Panel	66.8	68	67	66

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Worn as per age - Yes / Carpet - Worn, Scratch, Cut, Crack - Large / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Large / (R) Front Seat - Cut, Crack - Medium</p>	<p>Remarks (R) Front Door, Molding - Scratch - Medium / (R) Front Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Medium / Bonnet, Headlight - Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Large / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no LTO plate/ no tools and jack/ with warranty booklet and spare tire/ hazard issue</p>