

General Information

Date & Time: 11, Aug, 2025 18:30

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	12,850
Registration No.	NHM3349	Chassis No.	PA1B18F35R4238992
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.6	102	110	120
2	Boot Lid	113.6	110	116	115
3	Roof	103.7	105	107	101/102
4	Left Front Fender	98.1	98	97	100
5	Left Front Door	96.7	92	93	105
6	Center Panel Left				
7	Left Rear Door	114.6	118	125	101
8	Left Back Panel	114.0	126	116	100
9	Right Front Fender	102.8	104	105	100
10	Right Front Door	111.3	114	110	110
11	Center Panel Right				
12	Right Rear Door	109.0	101	110	116
13	Right Back Panel	113.0	111	102	126

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Seat - Worn - Yes / (R) Front Trim - Grime - Minimal / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Minimal / Console, Switchs, Vents - Loose, Deformed - Small / Ceiling - Grime - Minimal	Remarks Member (Bolted) - Dent - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Crack, Gap - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Dent - Medium / Roof - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
no warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on tail light