

General Information

Date & Time: 11, Aug, 2025 13:59

Make	Toyota	Model	Rush
YOM	2022	Odo Meter Reading	47,644
Registration No.	NIC8689	Chassis No.	MHKE8FF3PNK045274
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	139.6	147	137	135
2	Boot Lid	122.0	125	120	121
3	Roof	130.5	124	141	138/119
4	Left Front Fender	144.6	146	144	144
5	Left Front Door	148.3	140	145	160
6	Center Panel Left				
7	Left Rear Door	150.0	162	147	141
8	Left Back Panel	129.0	141	116	130
9	Right Front Fender	149.0	155	149	143
10	Right Front Door	116.0	122	116	110
11	Center Panel Right				
12	Right Rear Door	267.3	441	219	142
13	Right Back Panel	192.6	182	180	216

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : E	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Medium / (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Small / (R) Rear Trim - Grime - Medium / Rear Seat - Grime - Large / (L) Rear Trim - Grime - Small / Mat Other - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Large / (L) Front Floor Mat - Cut, Crack - Medium	Remarks (R) Step - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

Molds around the interior. Cut/crack on carpet driver side. With warranty booklet, spare tire and jack. Incomplete tools. Without seat cover. 1 key. With LTO plate. With dashcam.