

General Information

Date & Time: 12, Aug, 2025 10:21

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	38,622
Registration No.	NFR5345	Chassis No.	PA1B18F31R4252081
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	134.3	136	123	144
2	Boot Lid	121.0	128	123	112
3	Roof	122.7	130	131	110/120
4	Left Front Fender	127.3	126	124	132
5	Left Front Door	126.6	132	123	125
6	Center Panel Left				
7	Left Rear Door	133.0	140	125	134
8	Left Back Panel	129.3	111	152	125
9	Right Front Fender	131.6	129	146	120
10	Right Front Door	121.6	124	115	126
11	Center Panel Right				
12	Right Rear Door	124.0	118	122	132
13	Right Back Panel	125.0	122	127	126

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Trunk Room - Worn, Scratch, Cut, Crack - Small / Rear Seat - Grime - Medium / (L) Front Floor Mat - Worked - Large / (L) Front Seat - Grime - Small / Ceiling - Grime - Large / (R) Front Seat - Grime - Medium / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small</p>		<p>Remarks (R) Rear Fender, Molding - Repair mark - Yes / (R) Rear Door, Molding - Repair mark - Yes / (R) Front Fender, Molding - Dent - Large / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Dent - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Door, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Repair mark - Yes / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Minimal</p>	
Frame Evaluation :	D	Functional Evaluation :	A
<p>Remarks Right Front Inside (Rear Side) - Traces of Bending, or Marks of Panel Repair ? - Yes</p>		<p>Remarks Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate, with warranty booklet, with jack and incomplete tools, with spare tire, scratches on tail light, traces of adhesive on front windshield