

General Information

Date & Time: 12, Aug, 2025 10:26

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	43,717
Registration No.	DBI4913	Chassis No.	PA1B18F37P4213198
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	154.0	160	149	153
2	Boot Lid	142.3	140	140	147
3	Roof	140.7	139	138	149/137
4	Left Front Fender	133.6	136	134	131
5	Left Front Door	130.3	132	130	129
6	Center Panel Left				
7	Left Rear Door	136.0	138	141	129
8	Left Back Panel	146.0	149	140	149
9	Right Front Fender	137.6	140	136	137
10	Right Front Door	127.6	127	123	133
11	Center Panel Right				
12	Right Rear Door	131.6	122	130	143
13	Right Back Panel	135.3	128	135	143

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Small / (L) Front Seat - Grime - Minimal	Remarks (L) Rear Door, Molding - Dent - Small / Bonnet, Headlight - Scratch - Medium / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/with spare tire/with jack and tools/No reverse camera/No spare key/ No warranty booklet