

General Information

Date & Time: 18, Aug, 2025 17:44

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	32,184
Registration No.	NII9810	Chassis No.	PA1B18F3XP4202650
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	129.3	119	144	125
2	Boot Lid	112.0	108	110	118
3	Roof	105.0	107	103	104/106
4	Left Front Fender	106.6	106	108	106
5	Left Front Door	104.0	108	103	101
6	Center Panel Left				
7	Left Rear Door	151.6	147	154	154
8	Left Back Panel	112.3	114	108	115
9	Right Front Fender	114.0	111	120	111
10	Right Front Door	121.3	133	123	108
11	Center Panel Right				
12	Right Rear Door	113.0	108	103	128
13	Right Back Panel	120.6	115	118	129

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Small / (L) Front Seat - Worn - Yes / Overall Interior - Animal Hair - Yes / Rear Seat - Worn - Yes / (R) Front Trim - Grime - Minimal / (L) Front Floor Mat - Cut, Crack - Small / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Minimal</p>	<p>Remarks (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Small / Member (Bolted) - Dent - Yes / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Crack, Gap - Large / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet, with jack, incomplete tools, with spare tire, with LTO plate, scratches on taillight, uneven engine hood, possible flooding, left headlight with water</p>