

General Information

Date & Time: 19, Aug, 2025 10:37

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	21,629
Registration No.	DBJ7289	Chassis No.	PA1B18F3XP4225684
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.6	109	111	109
2	Boot Lid	110.0	104	113	113
3	Roof	99.4	102	103	93/100
4	Left Front Fender	102.1	98	101	107
5	Left Front Door	104.3	105	107	101
6	Center Panel Left				
7	Left Rear Door	111.0	113	103	117
8	Left Back Panel	113.6	123	110	108
9	Right Front Fender	111.6	110	114	111
10	Right Front Door	105.0	101	109	105
11	Center Panel Right				
12	Right Rear Door	102.8	98	103	108
13	Right Back Panel	112.0	105	109	122

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : B
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Minimal / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Grime - Small / (L) Front Seat - Grime - Small / Ceiling - Grime - Small</p>	<p>Remarks Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Crack, Gap - Medium / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Roof - Dent - Small / (R) Front Door, Molding - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Power Steering - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with jack and tools/No reverse camera/No spare key/with warranty booklet /unusual sound due to vibration/power steering wheel issue</p>