

## General Information

Date & Time: 19, Aug, 2025 14:27

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2022	<b>Odo Meter Reading</b>	126,075
<b>Registration No.</b>	NEM9819	<b>Chassis No.</b>	PA1B18F30M4162865
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Green		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	<b>118.0</b>	115	116	123
2	Boot Lid	<b>127.0</b>	116	142	123
3	Roof	<b>99.2</b>	101	97	100/99
4	Left Front Fender	<b>102.2</b>	106	100	101
5	Left Front Door	<b>101.3</b>	100	102	102
6	Center Panel Left				
7	Left Rear Door	<b>111.6</b>	126	109	100
8	Left Back Panel	<b>113.0</b>	122	107	110
9	Right Front Fender	<b>100.1</b>	101	100	99
10	Right Front Door	<b>101.3</b>	104	98	102
11	Center Panel Right				
12	Right Rear Door	<b>101.2</b>	101	96	107
13	Right Back Panel	<b>106.3</b>	102	101	116

**Overall Evaluation :**

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>          Trunk Room - Worn, Scratch, Cut, Crack - Small / Rear Seat - Grime - Large / (R) Front Seat - Worn - Yes / (L) Front Seat - Worn - Yes / (R) Front Trim - Grime - Small / (L) Front Floor Mat - Grime - Medium / (L) Front Trim - Grime - Medium / Knobs - Worn, Peel, Crack - Small / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Medium</p>	<p><b>Remarks</b>          Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / (L) Rear Fender, Molding - Scratch &amp; Dent - Small / Trunk Hood, Rear Gate - Scratch &amp; Dent - Medium / (R) Rear Fender, Molding - Scratch &amp; Dent - Medium / (R) Rear Door, Molding - Scratch &amp; Dent - Medium / (R) Front Door, Molding - Scratch &amp; Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Large / (R) Front Fender, Molding - Scratch &amp; Dent - Medium / Bonnet, Headlight - Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Fender, Molding - Scratch &amp; Dent - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Step, In-panel, Side Spoiler - Dent - Small / (L) Rear Door, Molding - Scratch - Minimal / Roof - Scratch &amp; Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
<p><b>Remarks</b>          Defects not found</p>	<p><b>Remarks</b>          Air Conditioner - Function - Weak / Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<b>Inspector Notes</b>
<p>with LTO plate/No spare tire/with warranty booklet/No jack and tools/possible flooding/No spare key/audio radio not function/head unit not working/ No reverse camera/battery weak/air-conditioning issue and abnormal vibration of engine when open the aircon.</p>