

## General Information

Date & Time: 15, Aug, 2025 16:06

<b>Make</b>	Toyota	<b>Model</b>	Innova
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	29,827
<b>Registration No.</b>	ZAD5263	<b>Chassis No.</b>	PA2JA8EM7R0147165
<b>CC</b>	2.8	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Wagon
<b>Colour</b>	Blackish Red Mica		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	96.1	108	95	85
2	Boot Lid	91.3	89	89	96
3	Roof	98.3	90	93	104/107
4	Left Front Fender	94.8	104	94	87
5	Left Front Door	100.2	100	102	99
6	Center Panel Left				
7	Left Rear Door	97.6	99	97	97
8	Left Back Panel	98.4	102	103	90
9	Right Front Fender	94.0	80	100	102
10	Right Front Door	93.8	94	101	87
11	Center Panel Right				
12	Right Rear Door	97.3	97	99	96
13	Right Back Panel	103.1	98	106	106

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Overall Interior - Smell - Yes / Rear Seat - Grime - Medium / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Rear Trim - Grime - Small / (R) Rear Trim - Grime - Small / Ceiling - Grime - Small</p>	<p><b>Remarks</b> Member (Bolted) - Dent - Yes / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch &amp; Dent - Small / (R) Rear Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / Trunk Hood, Rear Gate - Scratch &amp; Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Roof - Scratch - Small / (R) Front Fender, Molding - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Defects not found</p>

<p><b>Inspector Notes</b></p>
<p>With warranty booklet and LTO Plate, Spare tire and Jack, Incomplete Tools. Scratch headlight and tail light, adhesive marks on vehicle.,</p>