

General Information

Date & Time: 18, Aug, 2025 16:52

Make	Toyota	Model	Innova
YOM	2024	Odo Meter Reading	18,946
Registration No.	DBO3615	Chassis No.	PA2JA8EM3R0136101
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.5	111	118	97
2	Boot Lid	87.6	88	80	94
3	Roof	90.1	91	83	90/96
4	Left Front Fender	92.1	99	96	81
5	Left Front Door	93.4	95	93	93
6	Center Panel Left				
7	Left Rear Door	94.9	96	97	92
8	Left Back Panel	95.9	91	101	96
9	Right Front Fender	99.8	90	102	108
10	Right Front Door	97.1	99	98	95
11	Center Panel Right				
12	Right Rear Door	103.6	96	104	111
13	Right Back Panel	107.3	106	108	108

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	D
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Dashboard - Traces of Adhesive Tape - Yes</p>		<p>Remarks Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Dent - Small / Bonnet, Headlight - Scratch - Small / Roof - Dent - Large / (R) Rear Fender, Molding - Scratch - Small</p>	
Frame Evaluation :		Functional Evaluation :	
A		A	
<p>Remarks Defects not found</p>		<p>Remarks Defects not found</p>	

Inspector Notes
<p>no warranty booklet/ no jack and tools/ with sparetire and LTO plate/</p>