

General Information

Date & Time: 18, Aug, 2025 13:01

Make	Toyota	Model	Hiace
YOM	2024	Odo Meter Reading	75,551
Registration No.	DBP7994	Chassis No.	JTFJT02PXR5037554
CC	3.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.6	106	104	134
2	Boot Lid	111.3	112	108	114
3	Roof	132.2	147	112	121/149
4	Left Front Fender	149.0	151	150	146
5	Left Front Door	109.3	108	105	115
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	113.6	111	110	120
9	Right Front Fender	131.3	119	140	135
10	Right Front Door	116.6	122	116	112
11	Center Panel Right	127.0	141	129	111
12	Right Rear Door	116.6	106	121	123
13	Right Back Panel	116.0	116	123	109

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Smell - Yes / (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Ceiling - Grime - Small</p>	<p>Remarks (L) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Roof - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

Inspector Notes
<p>With LTO plate and Sparetire. No Tools and Jack, warranty booklet. Scratch headlight and tail light, Tint film on driver side window loose deformed, tow hook cover missing. worn tires and Sparetire. No reverse camera</p>