

General Information

Date & Time: 20, Aug, 2025 14:34

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	31,693
Registration No.	NFL9799	Chassis No.	PA1B18F32N4178955
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	122.3	125	118	124
2	Boot Lid	118.0	115	118	121
3	Roof	112.0	114	107	110/117
4	Left Front Fender	115.6	113	113	121
5	Left Front Door	109.0	106	108	113
6	Center Panel Left				
7	Left Rear Door	115.3	134	114	98
8	Left Back Panel	114.3	117	116	110
9	Right Front Fender	95.0	92	97	96
10	Right Front Door	106.5	114	106	100
11	Center Panel Right				
12	Right Rear Door	102.1	99	99	109
13	Right Back Panel	114.3	110	108	125

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Large / (L) Front Floor Mat - Worked - Small / Rear Seat - Grime - Small / (L) Front Seat - Grime - Small / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Small / Overall Interior - Smell - Yes / Overall Interior - Animal Hair - Yes</p>	<p>Remarks (L) Front Fender, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Medium / Member (Bolted) - Dent - Yes / (L) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Dent - Small / (R) Rear Fender, Molding - Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Dent - Minimal / (R) Front Fender, Molding - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Dent - Small / Roof - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate and warranty booklet and Sparetire, Jack and Incomplete Tools. Scratch headlight and Crack Tail light, busted Plate light, worn Sparetire.</p>