

## General Information

Date & Time: 18, Aug, 2025 08:26

Make	Suzuki	Model	XL7
YOM	2024	Odo Meter Reading	12,596
Registration No.	NKC6108	Chassis No.	MHYNC32S6RJ104329
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.5	116	99	99
2	Boot Lid	91.7	85	94	96
3	Roof	93.8	90	88	98/99
4	Left Front Fender	91.3	94	87	93
5	Left Front Door	99.7	103	97	99
6	Center Panel Left				
7	Left Rear Door	101.3	106	100	98
8	Left Back Panel	91.5	101	95	78
9	Right Front Fender	102.9	114	96	99
10	Right Front Door	112.3	116	105	116
11	Center Panel Right				
12	Right Rear Door	107.0	97	104	120
13	Right Back Panel	103.0	103	100	106

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

