

General Information

Date & Time: 16, Aug, 2025 15:55

Make	Toyota	Model	Innova
YOM	2025	Odo Meter Reading	9,241
Registration No.	BAG5977	Chassis No.	PA2JA8EMR0148488
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	95.5	89	105	93
2	Boot Lid	87.1	91	87	84
3	Roof	93.5	93	86	100/95
4	Left Front Fender	88.5	94	91	80
5	Left Front Door	92.7	90	92	96
6	Center Panel Left				
7	Left Rear Door	89.3	87	90	92
8	Left Back Panel	92.3	95	94	88
9	Right Front Fender	96.1	88	92	108
10	Right Front Door	92.4	91	95	92
11	Center Panel Right				
12	Right Rear Door	92.2	96	91	90
13	Right Back Panel	99.8	100	95	105

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Overall Interior - Smell - Yes	Remarks (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / Bonnet, Headlight - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
With LTO plate and warranty booklet and Sparetire, Jack and Tools, Scratch headlight and tail light.