

General Information

Date & Time: 25, Nov, 2024 06:45

Make	Toyota	Model	Hiace
YOM	2023	Mileage	148,096
Registration No.	VAB3803	Chassis No.	JTFJT02P1N0015790
CC	3.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	424.6	309	327	638
2	Boot Lid	92.6	90	96	92
3	Roof	76.3	69	81	77/79
4	Left Front Fender	89.8	89	92	89
5	Left Front Door	87.0	85	92	85
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	93.6	95	91	95
9	Right Front Fender	98.3	96	103	96
10	Right Front Door	84.4	77	91	85
11	Center Panel Right	99.3	99	98	101
12	Right Rear Door	97.0	99	96	97
13	Right Back Panel	101.4	95	100	110

Overall Evaluation :

D

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / Ceiling - Loose, Deformed - Large / Rear Seat - Missing - Yes / Carpet - Loose, Deformed - Medium	Remarks Bonnet - Repair Traces - Yes / (R) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Medium / Roof - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Small / Bonnet, Headlight - Repair mark - Yes / (L) Rear Wheel, Cover - Cap Missing - Yes / (L) Front Wheel, Cover - Cap Missing - Yes / (R) Front Wheel, Cover - Cap Missing - Yes / (R) Rear Wheel, Cover - Cap Missing - Yes / Bonnet, Headlight - Dent - Small
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
weak air-conditioning/ abnormal sound while shifting/ with warranty booklet/ without tools/ with spare tire/ with jack/ dirty carpet/