

General Information

Date & Time: 18, Aug, 2025 16:13

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	18,357
Registration No.	NKG3135	Chassis No.	PA1B18F35R4270390
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.0	121	103	115
2	Boot Lid	118.3	114	120	121
3	Roof	100.3	108	96	102/96
4	Left Front Fender	99.8	100	95	104
5	Left Front Door	105.3	104	105	107
6	Center Panel Left				
7	Left Rear Door	110.0	114	104	112
8	Left Back Panel	106.5	119	103	98
9	Right Front Fender	101.6	105	102	98
10	Right Front Door	95.6	92	101	94
11	Center Panel Right				
12	Right Rear Door	99.7	101	99	99
13	Right Back Panel	104.0	105	102	105

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Grime - Large / (R) Front Seat - Grime - Medium / Mat Other - Grime - Large / (L) Front Floor Mat - Grime - Medium</p>	<p>Remarks (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with warranty booklet, with spare tire, with jack and tools,with lto plate,1 key, traces of adhesive in all door</p>