


General Information

Date & Time: 23, Nov, 2024 13:11

Make	Toyota	Model	Vios
YOM	2022	Mileage	32,510
Registration No.	EAE7510	Chassis No.	PA1B18F34N4171246
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.3	114	108	121
2	Boot Lid	110.3	123	96	112
3	Roof	100.3	103	95	103/100
4	Left Front Fender	99.6	97	98	104
5	Left Front Door	106.6	108	110	102
6	Center Panel Left				
7	Left Rear Door	108.0	109	108	107
8	Left Back Panel	124.0	134	115	123
9	Right Front Fender	105.3	111	101	104
10	Right Front Door	105.6	105	101	111
11	Center Panel Right				
12	Right Rear Door	105.9	98	107	113
13	Right Back Panel	126.0	108	105	165

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Floor Mat - Grime - Small	Remarks Rear Bumper, Lamps, Panels - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with jack/no tools/no spare tire/no warranty booklets/no reverse camera/hairlines scratches