

## General Information

Date & Time: 19, Aug, 2025 15:42

<b>Make</b>	Toyota	<b>Model</b>	Raize
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	1,234
<b>Registration No.</b>	DBB6422	<b>Chassis No.</b>	MHKAB1BA1PJ044335
<b>CC</b>	1.2	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	SUV
<b>Colour</b>	Red		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet				
2	Boot Lid				
3	Roof				
4	Left Front Fender				
5	Left Front Door				
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel				
9	Right Front Fender				
10	Right Front Door				
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel				

**Overall Evaluation :**

E

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-weight: bold;">A</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-weight: bold;">N / A</span>
<div style="text-align: center;"> </div> <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	
<b>Remarks</b> Defects not found	<b>Remarks</b> Defects not found
<b>Frame Evaluation :</b> <span style="color: red; font-weight: bold;">N / A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-weight: bold;">N / A</span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Defects not found

<b>Inspector Notes</b>
no warranty booklet, no jack and tools, no spare tire, with LTO plate, (Interior and mileage can't be verified due to door locked and no keys)