

General Information

Date & Time: 19, Aug, 2025 15:42

Make	Toyota	Model	Hilux
YOM	2019	Odo Meter Reading	1,234
Registration No.	NCK2598	Chassis No.	MR0GB8DD3J1420675
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Red		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet				
2	Boot Lid				
3	Roof				
4	Left Front Fender				
5	Left Front Door				
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel				
9	Right Front Fender				
10	Right Front Door				
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel				

Overall Evaluation :

E

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	N / A
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>			
Remarks	Defects not found	Remarks	Defects not found
Frame Evaluation :	N / A	Functional Evaluation :	N / A
Remarks	Defects not found	Remarks	Defects not found

Inspector Notes
no warranty booklet, no jack and tools, with spare tire, no LTO plate, possible flooding, scratches on tail light, (Interior and mileage can't be verified due to door locked and no keys)