


General Information

Date & Time: 26, Aug, 2025 12:05

Make	Toyota	Model	Wigo
YOM	2025	Odo Meter Reading	1,571
Registration No.	NKM7436	Chassis No.	MHKAA1BCXRJ033647
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Orange		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	129.3	127	131	130
2	Boot Lid	96.8	103	97	90
3	Roof	85.2	85	79	86/91
4	Left Front Fender	101.9	99	99	108
5	Left Front Door	110.0	111	107	112
6	Center Panel Left				
7	Left Rear Door	105.2	114	100	102
8	Left Back Panel	92.8	95	89	95
9	Right Front Fender	104.6	127	99	88
10	Right Front Door	116.3	130	111	108
11	Center Panel Right				
12	Right Rear Door	101.3	89	99	117
13	Right Back Panel	90.4	98	88	85

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Small / (R) Front Seat - Grime - Minimal</p>	<p>Remarks (L) Rear Fender, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with jack No tools/with reverse camera/with spare key/with warranty booklet</p>