

## General Information

Date & Time: 28, Aug, 2025 14:23

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2018	<b>Odo Meter Reading</b>	52,051
<b>Registration No.</b>	A1W709	<b>Chassis No.</b>	PA1B19F39H4045698
<b>CC</b>	1.3	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Orange		

## Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet				
2	Boot Lid				
3	Roof				
4	Left Front Fender				
5	Left Front Door				
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel				
9	Right Front Fender				
10	Right Front Door				
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel				

**Overall Evaluation :**

**E**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	A	<b>Exterior Evaluation :</b>	N / A
			
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>			
<p><b>Remarks</b> (R) Front Seat - Grime - Small / Ceiling - Grime - Small / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / (L) Front Seat - Cigarette Burns - Burnt Minimal</p>		<p><b>Remarks</b> Defects not found</p>	
<b>Frame Evaluation :</b>	N / A	<b>Functional Evaluation :</b>	N / A
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Defects not found</p>	

<b>Inspector Notes</b>
<p>No LTO plate/with spare tire/ No warranty booklet/No reverse camera/with jack and incomplete tools, HPG RECOVER, WITH ORCR "DOUBLE REGISTRATION ". NO BATTERY.</p>