# Grading Report

## General Information

**Date & Time: 23, Nov, 2024 14:47**

| | | | |
|---|---|---|---|
| **Make** | Toyota | **Model** | Vios |
| **YOM** | 2022 | **Mileage** | 22,442 |
| **Registration No.** | CBK6545 | **Chassis No.** | PA1B18F36N4183544 |
| **CC** | 1.3 | **Transmission** | CVT |
| **Fuel Type** | Gas | **Type of Body** | Sedan |
| **Colour** | Blue | | |

## Body / Panel Condition

| # | Area | Thickness(um) | | | |
|---|---|---|---|---|---|
| | | Average | Value1 | Value2 | Value3/4 |
| 1 | Bonnet | **107.3** | 104 | 106 | 112 |
| 2 | Boot Lid | **101.3** | 101 | 98 | 105 |
| 3 | Roof | **96.8** | 102 | 89 | 107/90 |
| 4 | Left Front Fender | **105.0** | 116 | 94 | 105 |
| 5 | Left Front Door | **100.8** | 108 | 100 | 95 |
| 6 | Center Panel Left | | | | |
| 7 | Left Rear Door | **146.3** | 135 | 145 | 159 |
| 8 | Left Back Panel | **169.6** | 186 | 161 | 162 |
| 9 | Right Front Fender | **100.7** | 100 | 95 | 108 |
| 10 | Right Front Door | **96.4** | 97 | 95 | 97 |
| 11 | Center Panel Right | | | | |
| 12 | Right Rear Door | **101.8** | 97 | 106 | 103 |
| 13 | Right Back Panel | **101.0** | 93 | 99 | 112 |

## Overall Evaluation : A

**Disclaimer**

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

# Grading Report

| Interior Evaluation : B | Exterior Evaluation : B |
|---|---|
| a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain | A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap |
| **Remarks**<br>(L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Medium | **Remarks**<br>(L) Rear Fender - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Dent - Small / (L) Rear Door, Molding - Scratch - Medium |
| **Frame Evaluation : A** | **Functional Evaluation : A** |
| **Remarks**<br>Defects not found | **Remarks**<br>Spare Key - Issue - Unexist |

| Inspector Notes |
|---|
| with spare tire/tools/jack/no reverse camera/no warranty booklets |