

General Information

Date & Time: 29, Aug, 2025 09:46

Make	Suzuki	Model	Ertiga
YOM	2025	Odo Meter Reading	1,234
Registration No.	NNV8256	Chassis No.	MHYNC32S6SJ102814
CC	1.3	Transmission	A/T
Fuel Type	Hybrid	Type of Body	Wagon
Colour	Brown		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet				
2	Boot Lid				
3	Roof				
4	Left Front Fender				
5	Left Front Door				
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel				
9	Right Front Fender				
10	Right Front Door				
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel				

Overall Evaluation :

E

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	N / A
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>			
Remarks	Defects not found	Remarks	Defects not found
Frame Evaluation :	N / A	Functional Evaluation :	N / A
Remarks	Defects not found	Remarks	Defects not found

Inspector Notes
no warranty booklet, no jack and tools, with spare tire, with LTO plate, (Interior and mileage can't be verified due to door locked and no keys),Towed unit