

General Information

Date & Time: 04, Sep, 2025 08:19

Make	Toyota	Model	Wigo
YOM	2025	Odo Meter Reading	7,459
Registration No.	DBQ7516	Chassis No.	MHKAA1BC6RJ027327
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.6	113	119	112
2	Boot Lid	84.3	84	83	87
3	Roof	83.4	79	86	85/84
4	Left Front Fender	104.8	98	108	108
5	Left Front Door	108.6	101	112	113
6	Center Panel Left				
7	Left Rear Door	101.3	112	100	93
8	Left Back Panel	89.3	97	86	85
9	Right Front Fender	97.6	109	97	87
10	Right Front Door	111.0	114	112	107
11	Center Panel Right				
12	Right Rear Door	103.0	99	103	107
13	Right Back Panel	90.7	95	91	87

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (R) Rear Trim - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Seat - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Minimal	Remarks (L) Front Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch - Medium / (R) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/with jack/No tools/with reverse camera/No spare key/with warranty booklet/ front left bumper damage