

General Information

Date & Time: 09, Sep, 2025 15:22

Make	Toyota	Model	Vios
YOM	2021	Odo Meter Reading	116,268
Registration No.	DAY1625	Chassis No.	PA1B18F32L4129199
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	299.3	259	248	391
2	Boot Lid	165.3	129	205	162
3	Roof	93.3	91	89	93/100
4	Left Front Fender	240.6	237	245	240
5	Left Front Door	193.3	216	174	190
6	Center Panel Left				
7	Left Rear Door	158.3	147	138	190
8	Left Back Panel	264.0	161	468	163
9	Right Front Fender	225.6	219	227	231
10	Right Front Door	136.6	132	145	133
11	Center Panel Right				
12	Right Rear Door	90.1	92	87	91
13	Right Back Panel	117.3	102	123	127

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / Overall Interior - Smell - Yes / Overall Interior - Worn as per age - Yes / (R) Rear Trim - Cut, Crack - Minimal / (R) Front Trim - Grime - Medium / (L) Front Trim - Grime - Large / Console, Switches, Vents - Loose, Deformed - Medium / Ceiling - Grime - Medium</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Repair mark - Yes / Overall Exterior - Faded(Color, Gloss) - Yes / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Minimal / Bonnet, Headlight - Crack, Gap - Large / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : E
<p>Remarks Defects not found</p>	<p>Remarks Power Steering - Issue - Yes / Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes</p>

<p>Inspector Notes</p>
<p>no warranty booklet, no jack and tools, with spare tire, with LTO plate, scratched and cracked tail light, possible flooding, plate and park light issue, room lamp issue, air-con issue, abnormal noise on engine and transmission, power steering issue due to weak battery, mould on overall interior</p>