

General Information

Date & Time: 08, Sep, 2025 18:08

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	26,044
Registration No.	JAQ1730	Chassis No.	PA1B18F34P4227916
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.6	106	102	100
2	Boot Lid	97.4	97	97	98
3	Roof	86.5	88	91	80/87
4	Left Front Fender	94.5	99	92	93
5	Left Front Door	99.1	96	97	104
6	Center Panel Left				
7	Left Rear Door	97.5	99	92	101
8	Left Back Panel	101.3	108	100	96
9	Right Front Fender	100.1	99	100	101
10	Right Front Door	97.7	96	97	100
11	Center Panel Right				
12	Right Rear Door	100.0	103	95	102
13	Right Back Panel	105.3	94	101	121

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (R) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Small	Remarks (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
LTO plate not original/with spare tire/No reverse camera/with jack No tools/No warranty booklet