

General Information

Date & Time: 04, Sep, 2025 13:43

Make	Toyota	Model	Wigo
YOM	2024	Odo Meter Reading	28,342
Registration No.	DBO4227	Chassis No.	MHKAA1BC7PJ012297
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Yellow		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.6	122	130	113
2	Boot Lid	100.3	101	102	98
3	Roof	104.7	100	110	107/102
4	Left Front Fender	103.0	104	107	98
5	Left Front Door	104.9	102	100	113
6	Center Panel Left				
7	Left Rear Door	106.2	115	109	95
8	Left Back Panel	101.1	102	96	105
9	Right Front Fender	96.5	100	102	88
10	Right Front Door	104.3	118	100	95
11	Center Panel Right				
12	Right Rear Door	110.3	99	115	117
13	Right Back Panel	100.0	98	94	108

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (R) Front Floor Mat - Grime - Small / Ceiling - Grime - Medium</p>	<p>Remarks (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Modified - Minimal / (R) Front Fender, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Rear Bumper, Lamps, Panels - Modified - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Modified - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

Inspector Notes	
no warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on tail light and headlight	