

General Information

Date & Time: 04, Sep, 2025 10:07

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	48,696
Registration No.	NFR6580	Chassis No.	PA1B18F36R4253341
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.6	116	113	106
2	Boot Lid	105.3	105	105	106
3	Roof	106.9	100	130	96/102
4	Left Front Fender	102.0	107	98	101
5	Left Front Door	100.4	100	98	103
6	Center Panel Left				
7	Left Rear Door	106.3	109	105	105
8	Left Back Panel	114.3	122	115	106
9	Right Front Fender	110.6	114	108	110
10	Right Front Door	105.0	106	101	108
11	Center Panel Right				
12	Right Rear Door	106.0	100	110	108
13	Right Back Panel	107.3	101	107	114

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Missing - Yes / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Medium / (L) Front Trim - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Floor Mat - Cut, Crack - Medium / Ceiling - Grime - Small</p>	<p>Remarks Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with reverse camera/with warranty booklet/with jack/No tools/with spare key</p>