

## General Information

Date & Time: 03, Dec, 2024 15:03

<b>Make</b>	Toyota	<b>Model</b>	Innova
<b>YOM</b>	2024	<b>Mileage</b>	17,286
<b>Registration No.</b>	DBM4909	<b>Chassis No.</b>	PA2JA8EM5R0138285
<b>CC</b>	2.8	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	MPV
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	129.6	134	126	129
2	Boot Lid	83.0	84	80	84
3	Roof	89.4	95	90	82/91
4	Left Front Fender	98.6	103	98	95
5	Left Front Door	96.0	97	98	94
6	Center Panel Left				
7	Left Rear Door	93.6	97	93	90
8	Left Back Panel	97.2	97	99	96
9	Right Front Fender	98.7	97	100	100
10	Right Front Door	96.7	96	95	100
11	Center Panel Right				
12	Right Rear Door	97.2	92	100	100
13	Right Back Panel	106.3	108	106	105

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>B</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Overall Interior - Smell - Yes / Mat Other - Grime - Medium / Ceiling - Grime - Small</p>	<p><b>Remarks</b> (R) Rear Fender, Molding - Scratch &amp; Dent - Small / (R) Rear Door, Molding - Scratch &amp; Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / Front Windshield - Scratch, Stone chip - Small</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>swirlmarks and hairline scratches around the exterior. with tools,warranty booklet and user manual.</p>