

General Information

Date & Time: 08, Sep, 2025 14:46

Make	Toyota	Model	Vios
YOM	2018	Odo Meter Reading	67,646
Registration No.	NCW1041	Chassis No.	PA1B19F38J4064168
CC	1.3	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Orange		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	120.6	117	127	118
2	Boot Lid	120.0	117	119	124
3	Roof	112.7	109	114	118/110
4	Left Front Fender	122.3	111	120	136
5	Left Front Door	133.3	133	140	127
6	Center Panel Left				
7	Left Rear Door	171.0	149	146	218
8	Left Back Panel	470.3	647	523	241
9	Right Front Fender	127.3	138	126	118
10	Right Front Door	126.3	119	122	138
11	Center Panel Right				
12	Right Rear Door	123.6	127	120	124
13	Right Back Panel	127.3	133	119	130

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Small / Rear Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Cut, Crack - Medium / Ceiling - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Minimal / Overall Interior - Smell - Yes</p>	<p>Remarks (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Door, Molding - Repair mark - Yes / Trunk Hood, Rear Gate - Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Power Window (each) - Stuck, Gap - Yes / Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>LTO plate not original/with spare tire/No reverse camera/No spare key/front right window issue/with jack / No tools/ No warranty booklet/audio radio not working</p>