

General Information

Date & Time: 10, Sep, 2025 09:32

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	89,207
Registration No.	NER9540	Chassis No.	PA1B18F3XN4171378
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.3	117	113	113
2	Boot Lid	107.3	106	105	111
3	Roof	102.6	111	96	101/102
4	Left Front Fender	100.0	99	101	100
5	Left Front Door	109.3	105	114	109
6	Center Panel Left				
7	Left Rear Door	107.0	113	106	102
8	Left Back Panel	117.6	131	108	114
9	Right Front Fender	98.5	106	96	94
10	Right Front Door	107.3	117	101	104
11	Center Panel Right				
12	Right Rear Door	101.2	97	100	107
13	Right Back Panel	105.3	106	104	106

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / Rear Seat - Grime - Large / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Seat - Grime - Medium / Steering Wheel - Worn, Peel, Crack - Small / Knobs - Worn, Peel, Crack - Small / Ceiling - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes	Remarks Trunk Hood, Rear Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Dent - Small / (L) Rear Door, Molding - Dent - Small / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : D
Remarks Defects not found	Remarks Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Brake Pedal - Function - Weak / Spare Key - Issue - Unexist

Inspector Notes
No LTO plate/with spare tire/with jack and incomplete tools/ No warranty booklet/No reverse camera /No spare key/brake pedal issue/air-conditioning issue/bonnet hood issue