

General Information

Date & Time: 10, Sep, 2025 13:03

Make	Toyota	Model	Innova
YOM	2024	Odo Meter Reading	125,198
Registration No.	DBO9652	Chassis No.	PA2JA8EM2R0143315
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.0	117	119	115
2	Boot Lid	99.7	105	106	88
3	Roof	94.3	95	99	97/87
4	Left Front Fender	102.6	103	105	100
5	Left Front Door	99.6	96	111	92
6	Center Panel Left				
7	Left Rear Door	100.6	100	102	100
8	Left Back Panel	103.5	110	97	104
9	Right Front Fender	97.1	96	99	97
10	Right Front Door	97.9	100	103	91
11	Center Panel Right				
12	Right Rear Door	103.0	100	102	107
13	Right Back Panel	107.0	103	102	116

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : E	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Trunk Room - Worn, Scratch, Cut, Crack - Large / Rear Seat - Grime - Large / (L) Rear Trim - Grime - Medium / Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / (L) Front Trim - Grime - Medium / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / (L) Front Seat - Grime - Small / (R) Front Trim - Grime - Large / (R) Front Seat - Grime - Medium / (R) Rear Trim - Grime - Large / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / Ceiling - Grime - Small</p>	<p>Remarks Member (Bolted) - Dent - Yes / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Dent - Large / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Dent - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Crack, Gap - Large / (R) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Medium</p>
Frame Evaluation : B	Functional Evaluation : A
<p>Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes</p>	<p>Remarks Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, no warranty booklet, no jack and tools, with spare tire, scratches on headlight and tail light, busted tail light, busted plate light, busted headlight, traces of molds on interior</p>