

General Information

Date & Time: 08, Sep, 2025 12:32

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	6,392
Registration No.	NHN6300	Chassis No.	PA1B18F36R4243327
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.3	114	105	103
2	Boot Lid	108.0	101	106	117
3	Roof	104.6	103	109	93/113
4	Left Front Fender	99.1	95	98	104
5	Left Front Door	99.0	102	99	96
6	Center Panel Left				
7	Left Rear Door	104.6	107	106	101
8	Left Back Panel	109.0	117	107	103
9	Right Front Fender	108.3	114	105	106
10	Right Front Door	110.0	111	105	114
11	Center Panel Right				
12	Right Rear Door	112.0	105	112	119
13	Right Back Panel	112.6	108	111	119

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Small / (R) Front Trim - Grime - Minimal / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Small / (R) Mirror - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with reverse camera/with jack and incomplete tools/ with spare key</p>