

General Information

Date & Time: 08, Sep, 2025 12:54

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	23,653
Registration No.	NJF2989	Chassis No.	PA1B18F34R4276942
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.3	114	111	112
2	Boot Lid	105.0	110	105	100
3	Roof	109.4	111	104	97/126
4	Left Front Fender	100.0	101	102	97
5	Left Front Door	107.6	101	118	104
6	Center Panel Left				
7	Left Rear Door	109.6	115	114	100
8	Left Back Panel	112.6	118	111	109
9	Right Front Fender	99.6	97	97	105
10	Right Front Door	115.0	123	119	103
11	Center Panel Right				
12	Right Rear Door	103.6	102	106	103
13	Right Back Panel	108.3	104	114	107

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Mat Other - Worked - Small / (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Small / (L) Front Floor Mat - Worked - Small / (L) Front Floor Mat - Cut, Crack - Small / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Minimal / (L) Front Trim - Grime - Small / Ceiling - Crinkle - Small / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Minimal</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Large / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Mirror - Scratch - Minimal / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / Member (Bolted) - Dent - Yes / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>with warranty booklet, with jack, incomplete tools, with spare tire, with LTO plate, scratched and cracked tail light</p>