

General Information

Date & Time: 06, Sep, 2025 15:02

Make	Toyota	Model	Rush
YOM	2025	Odo Meter Reading	5,156
Registration No.	NJF1187	Chassis No.	MHKE8FF3PRK063467
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.3	113	111	107
2	Boot Lid	141.3	140	152	132
3	Roof	99.9	103	94	113/90
4	Left Front Fender	101.3	101	100	103
5	Left Front Door	108.0	110	105	109
6	Center Panel Left				
7	Left Rear Door	105.6	109	106	102
8	Left Back Panel	98.4	100	100	96
9	Right Front Fender	98.0	105	93	97
10	Right Front Door	103.0	110	103	96
11	Center Panel Right				
12	Right Rear Door	98.7	96	100	101
13	Right Back Panel	89.8	84	91	94

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Overall Interior - Smell - Yes	Remarks (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
With LTO plate and Sparetire and Jack and Incomplete Tools, No warranty booklet and Scratch headlight and tail light.