

General Information

Date & Time: 08, Sep, 2025 15:40

Make	Toyota	Model	Wigo
YOM	2018	Odo Meter Reading	102,237
Registration No.	A5M432	Chassis No.	MHKA4DF5FJJ1015752
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	226.0	414	134	130
2	Boot Lid	116.6	109	112	129
3	Roof	226.6	59	159	618/71
4	Left Front Fender	144.0	153	138	141
5	Left Front Door	133.6	127	123	151
6	Center Panel Left				
7	Left Rear Door	308.3	132	218	575
8	Left Back Panel	523.3	174	680	716
9	Right Front Fender	192.6	207	182	189
10	Right Front Door	195.6	191	186	210
11	Center Panel Right				
12	Right Rear Door	759.0	214	904	1,159
13	Right Back Panel	167.6	186	154	163

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
Remarks		Remarks	
<p>Mat Other - Missing - Yes / (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Ceiling - Grime - Medium / (L) Front Trim - Cut, Crack - Small / (R) Front Trim - Cut, Crack - Small / (L) Rear Trim - Cut, Crack - Small / (R) Rear Trim - Cut, Crack - Small / Rear Seat - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Overall Interior - Smell - Yes / Overall Interior - Worn as per age - Yes / Overall Interior - Animal Hair - Yes / Dashboard - Traces of Adhesive Tape - Yes / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / Glove Box - Loose, Deformed - Small / Steering Wheel - Worn, Peel, Crack - Small / Trunk Room - Loose, Deformed - Small</p>		<p>(R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair mark - Yes / Roof - Repair mark - Yes / Bonnet, Headlight - Repair mark - Yes / Front Bumper, Grille, Lamps - Repair mark - Yes / (R) Front Fender, Molding - Repair mark - Yes / (R) Front Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Fender, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Door, Molding - Repair mark - Yes / (L) Front Door, Molding - Repair mark - Yes / (L) Front Fender, Molding - Repair mark - Yes / (L) Step, In-panel, Side Spoiler - Repair mark - Yes / (R) Step, In-panel, Side Spoiler - Repair mark - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes</p>	
Frame Evaluation :	B	Functional Evaluation :	E
Remarks		Remarks	
<p>Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes</p>		<p>Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Shift Shock - Function - Weak / Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist</p>	

Inspector Notes
<p>No LTO plate, Jack and Tools, No warranty booklet, scratch headlight and tail, no Spare tire, worn tires, towed unit, Key issue unlock button, no trunk room cover, HPG RECOVERED,</p>