

## General Information

Date & Time: 24, Feb, 2026 17:59

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2019	<b>Odo Meter Reading</b>	49,503
<b>Registration No.</b>	NBG1370	<b>Chassis No.</b>	PA1B23F38J6006086
<b>CC</b>	1.5	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.6	127	99	112
2	Boot Lid	127.0	127	123	131
3	Roof	116.7	127	108	111/121
4	Left Front Fender	417.3	382	535	335
5	Left Front Door	258.0	278	249	247
6	Center Panel Left				
7	Left Rear Door	203.3	212	198	200
8	Left Back Panel	173.6	179	161	181
9	Right Front Fender	660.0	326	1,142	512
10	Right Front Door	301.0	299	252	352
11	Center Panel Right				
12	Right Rear Door	257.0	222	224	325
13	Right Back Panel	219.0	208	204	245

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

