

General Information

Date & Time: 07, Dec, 2024 08:41

Make	Toyota	Model	Vios
YOM	2023	Mileage	9,065
Registration No.	NIT7790	Chassis No.	PA1B18F33P4220665
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	BLACKISH RED MICA		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.4	110	99	104
2	Boot Lid	105.9	100	110	108
3	Roof	99.6	110	97	98/94
4	Left Front Fender	102.6	109	98	101
5	Left Front Door	91.0	95	92	87
6	Center Panel Left				
7	Left Rear Door	96.8	100	95	96
8	Left Back Panel	105.6	123	103	91
9	Right Front Fender	93.0	94	90	96
10	Right Front Door	93.5	93	93	95
11	Center Panel Right				
12	Right Rear Door	96.5	92	94	104
13	Right Back Panel	96.5	95	95	100

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes	Remarks (L) Rear Fender, Molding - Scratch - Minimal / Member (Bolted) - Dent - Yes
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with spare tire/ no warranty booklet and tools/ with jack/ no reverse camera