

General Information

Date & Time: 09, Oct, 2025 18:47

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	10,876
Registration No.	FAO6493	Chassis No.	PA1B18F3XP4208853
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.3	114	114	118
2	Boot Lid	111.3	107	105	122
3	Roof	102.6	118	100	92/101
4	Left Front Fender	114.9	96	102	147
5	Left Front Door	106.0	102	105	111
6	Center Panel Left				
7	Left Rear Door	112.3	127	113	97
8	Left Back Panel	120.6	124	116	122
9	Right Front Fender	102.6	107	99	102
10	Right Front Door	93.3	100	90	90
11	Center Panel Right				
12	Right Rear Door	106.3	95	102	122
13	Right Back Panel	103.8	108	93	110

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Worn - Yes / (R) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Small / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Grime - Small / Mat Other - Grime - Small	Remarks (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Small / (R) Mirror - Crack - Damaged / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Door, Molding - Repair mark - Yes / (L) Rear Door, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Modified - Small / (R) Front Fender, Molding - Modified - Small / Rear Bumper, Lamps, Panels - Modified - Small / (L) Rear Fender, Molding - Modified - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Large
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

no warranty booklet, no jack and tools, with spare tire, with LTO plate, scratches on tail light, right side mirror loose, battery weak