


General Information

Date & Time: 10, Oct, 2025 20:33

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	26,649
Registration No.	FAP6732	Chassis No.	PA1B18F38P4222573
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.7	112	97	108
2	Boot Lid	103.2	97	103	110
3	Roof	99.6	97	90	108/104
4	Left Front Fender	94.4	95	95	93
5	Left Front Door	93.0	92	88	99
6	Center Panel Left				
7	Left Rear Door	101.1	105	99	100
8	Left Back Panel	108.0	112	105	107
9	Right Front Fender	95.7	94	98	95
10	Right Front Door	97.2	102	95	94
11	Center Panel Right				
12	Right Rear Door	101.6	100	101	104
13	Right Back Panel	100.5	95	100	107

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium / (R) Front Trim - Grime - Medium / (L) Front Trim - Grime - Small / Mat Other - Grime - Small / (L) Front Floor Mat - Grime - Small	Remarks (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
Without warranty booklet. Incomplete tools. With spare tire,jack and leather seat cover. 1 key. No LTO plate.