

General Information

Date & Time: 09, Oct, 2025 18:44

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	5,135
Registration No.	FAQ6069	Chassis No.	PA1B18F34R4262894
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.3	114	107	122
2	Boot Lid	101.0	98	99	106
3	Roof	93.7	87	104	89/95
4	Left Front Fender	86.4	90	87	82
5	Left Front Door	91.8	91	90	95
6	Center Panel Left				
7	Left Rear Door	93.0	100	91	88
8	Left Back Panel	98.9	101	99	97
9	Right Front Fender	99.0	94	101	102
10	Right Front Door	94.1	91	100	92
11	Center Panel Right				
12	Right Rear Door	96.3	103	91	96
13	Right Back Panel	101.2	101	96	107

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Worked - Small	Remarks (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes

With warranty booklet, spare tire and seat cover. Without jack and tools. 1 key. With LTO plate.