

General Information

Date & Time: 18, Sep, 2025 18:31

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	14,146
Registration No.	FAR4499	Chassis No.	PA1B18F39R4247906
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.0	106	101	111
2	Boot Lid	95.1	95	90	100
3	Roof	97.5	99	108	87/97
4	Left Front Fender	90.0	99	88	84
5	Left Front Door	91.8	94	94	88
6	Center Panel Left				
7	Left Rear Door	93.3	99	90	91
8	Left Back Panel	104.5	113	101	100
9	Right Front Fender	104.0	104	106	102
10	Right Front Door	94.1	95	96	92
11	Center Panel Right				
12	Right Rear Door	96.9	93	97	101
13	Right Back Panel	98.5	99	94	103

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Minimal / (R) Front Floor Mat - Grime - Minimal / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Cut, Crack - Small</p>	<p>Remarks (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>With warranty booklet, spare tire, jack, tools and seat cover. 3 keys. With LTO plate.</p>