

General Information

Date & Time: 24, Sep, 2025 20:31

Make	Toyota	Model	Lite Ace
YOM	2024	Odo Meter Reading	1,862
Registration No.	FAR6518	Chassis No.	MHKU3FE10RK007798
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	62.1	59	68	60
2	Boot Lid	66.9	95	56	51
3	Roof	62.3	54	70	62/63
4	Left Front Fender	66.8	73	61	67
5	Left Front Door	65.2	70	63	62
6	Center Panel Left	80.2	81	77	83
7	Left Rear Door				
8	Left Back Panel	100.5	86	123	93
9	Right Front Fender	66.2	66	66	67
10	Right Front Door	62.4	57	60	70
11	Center Panel Right	66.2	75	57	67
12	Right Rear Door				
13	Right Back Panel	89.6	87	87	95

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Side Gate - Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Minimal / Rear Gate - Scratch - Minimal / Cargo Bed Floor - Scratch - Medium / (L) Side Gate - Dent - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Center Panel - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Front Panel - Scratch - Minimal / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>no warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on tail light</p>