

General Information

Date & Time: 15, Jan, 2026 15:19

Make	Toyota	Model	Lite Ace
YOM	2024	Odo Meter Reading	5,867
Registration No.	FAR5489	Chassis No.	MHKB3FE10RK003590
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Utility Cargo
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	47.2	45	50	46
2	Boot Lid	70.2	47	64	100
3	Roof	55.4	56	45	61/60
4	Left Front Fender	48.9	48	46	53
5	Left Front Door	45.4	43	49	45
6	Center Panel Left	51.7	52	54	49
7	Left Rear Door	47.5	48	46	48
8	Left Back Panel	50.3	46	52	53
9	Right Front Fender	54.6	60	50	54
10	Right Front Door	44.4	40	44	49
11	Center Panel Right	68.8	50	50	107
12	Right Rear Door	50.7	50	50	53
13	Right Back Panel	50.0	44	49	58

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Trim - Grime - Large / (R) Front Seat - Grime - Medium / Ceiling - Grime - Minimal / Dashboard - Worn, Scratch, Cut, Crack - Small / (L) Front Seat - Grime - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Small / Trunk Room - Worn, Scratch, Cut, Crack - Large / (L) Front Trim - Grime - Large</p>	<p>Remarks (L) Rear Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Roof - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/No spare key/No reverse camera/with jack and incomplete tools/No warranty/No seat cover</p>